



*Italian Ministry of Infrastructure and Transport*

# ITALIAN MARITIME INVESTIGATIVE BODY ON MARINE ACCIDENTS

MARINE ACCIDENT  
INVESTIGATION  
C/S COSTA CONCORDIA  
13<sup>th</sup> January 2012

*MSC90*  
*London - May 18<sup>th</sup>, 2012*



# TABLE OF CONTENTS

1. ITALIAN MARITIME INVESTIGATIVE BODY
2. INVESTIGATIVE ACTIVITIES - *Preamble*
3. FACTUAL INFORMATION
  - 3.1 *The Accident*
  - 3.2 *Crew members*
  - 3.3 *Passengers*
  - 3.4 *Survival Crafts*
4. ANALYSIS
  - 4.1 *Methodology of C/s Costa Concordia Marine Accident Investigation*
  - 4.2 *Ship Stability in damage condition – NAPA Simulation on C/s Costa SERENA*
5. INVESTIGATION UNDERWAY
  - 5.1 *Preliminary remarks*
  - 5.2 *Issues still under investigation*



# 1. ITALIAN MARITIME INVESTIGATIVE BODY

## THE INVESTIGATIVE BODY :

- acts under the Ministry of Infrastructure and Transport (*the Administration*)
- carries out investigations and reports to the Administration on the circumstances and causes related to the accidents or incidents.
- is responsible for collecting and analyzing data concerning maritime safety and uses the investigations' outcomes for the enhancement of safety of navigation and maritime transport.
- is responsible for the maintenance and updating of the European Marine Casualty Platform (EMCIP) and Global Integrated Shipping Information (GISIS).





# 2. INVESTIGATIVE ACTIVITIES

## - PREAMBLE -

INVESTIGATION	COMPETENT ADMINISTRATION	LEGAL BASIS	TASK
<b><u>ADMINISTRATIVE</u></b>	Italian Coastguard	Italian Navigation Code	determination of the causes and possible responsibilities arising from the accident
<b><u>TECHNICAL MARINE SAFETY</u></b>	Ministry of Infrastructure and Transport  <b>Maritime Investigative Body</b>	National Act n.165 dated 6-Sep-2011 implementing Directive 2009/18/EC and SOLAS - IMO Code	Identification of the causes and circumstances determining the accident, from a strictly technical perspective. Reporting the outcomes for possible follow-up action to improve maritime safety
<b><u>CRIMINAL</u></b>	Prosecutor	Criminal Law	Ascertainment of responsibilities and guilties

## 2. INVESTIGATIVE ACTIVITIES

### - PREAMBLE -

- ❑ Legal Preeminence of Criminal Investigation above the other ones
- ❑ Cooperation between the Criminal and Technical Inquiries, however some due dates provided by law are to be respected.

**Next 21<sup>st</sup> July**, Experts of the Prosecutor will provide the outcome of the VDR analysis and the investigative body will have complete access to the data.



1. ITALIAN MARITIME INVESTIGATIVE BODY

2. INVESTIGATIVE ACTIVITIES - *Preamble*

3. **FACTUAL INFORMATION**

**3.1 *The Accident***

**3.2 *Crew members***

**3.3 *Passengers***

**3.4 *Survival Crafts***

4. ANALYSIS

4.1 *Methodology of C/s Costa Concordia Marine Accident Investigation*

4.2 *Ship Stability in damage condition – NAPA Simulation on C/s Costa SERENA*

5. INVESTIGATION UNDERWAY

5.1 *Preliminary remarks*

5.2 *Issues still under investigation*



# 3. FACTUAL INFORMATION

## 3.1 The Accident


**January 13th, 2012**

- C/S Costa CONCORDIA (the “Ship”) docks at the port of Civitavecchia
- 7.00 pm: scheduled departure for Savona

*Civitavecchia-Savona: last leg of her seven - days cruise.*

### **Before departure**

Planning of a **touristic sailing course** envisaging an approach to the Island of Giglio – up to a bathymetric contour line at 10 meters depth





# 3. FACTUAL INFORMATION

## 3.1 The Accident

The **voyage plan** schedules:

- ❑ leaving the funnel-shaped exit of the Port of Civitavecchia
- ❑ proceeding  $302^\circ$
- ❑ turning to  $278^\circ$  - abeam *Punta Secca* (Island of Giannutri), at a distance of 4,5 miles from it
- ❑ altering the course to  $334^\circ$ , where *Punta della Torricella* (Island of Giglio) is bearing  $239^\circ$  from the ship, at a distance of 0,9 miles.






# 3. FACTUAL INFORMATION

## 3.1 The Accident

Passage 0,5 miles from the bathymetric limit of 10 meters depth, abeam “Le Scole Reef” (Island of Giglio).

The Ship's **Integrated Navigation System** (Nautical Chart nr. 6 - scale 1:100.000 of Italian Hydrographic Service and the Electronic Cartography – ECDIS ) reports the planned course.



**January 13<sup>th</sup>, 2012 07.18 pm:**


**Actual departure from the port of Civitavecchia bound for Savona** 9

# 3. FACTUAL INFORMATION

## 3.1 The Accident

Ship's position at 09.00 pm according to the *Automatic Identification System (AIS)*

- Coordinates: Lat 42°18'25"N - Lon 011°10'48"E
- Bearing of 230° Punta Secca - Island of Giannutri
- Distance: 4,2 miles
- True course: 302°
- Speed: 15.8 knots




# 3. FACTUAL INFORMATION

## 3.1 The Accident

09.03 pm

the Ship starts attending to port until 09.11 pm, when she gets to a position of

- Coordinates:  $42^{\circ}19'18''\text{N}$  -  $011^{\circ}06'57''\text{E}$  ;
- Heading of  $279^{\circ}$ ,
- Speed: 16 knots;
- Heading towards the Island of Giglio.




# 3. FACTUAL INFORMATION

## 3.1 The Accident

- Five minutes after completing the turning to port manoeuvre, the Chief Officer on duty contacts the Ship Master who arrives to the bridge and takes over the con.
- He takes the manual steering and orders the helmsman to keep unchanged the course.
- Radars under observation.

**At 09.37 pm** : Ship's position is  $42^{\circ}20'12''\text{N}$  ;  $010^{\circ}58'19''\text{E}$  (about 1,8 mile East Punta della Torricella - Island of Giglio), at a speed of 15.4 knots.

She turns to starboard in order to make the safety passage close to the Island.




# 3. FACTUAL INFORMATION

## 3.1 The Accident

**09.44 pm**

- Manoeuvre still ongoing
- Ship's position:  $42^{\circ}21'05''\text{N}$ ;  $010^{\circ}56' \text{E}$   
her bow heading to "Le Scole Reef" - 0,3 miles off the rocks
- Speed: 16 knots





# 3. FACTUAL INFORMATION

## 3.1 The Accident

The Yaw Radius is such that the Ship is situated 0.5 miles south-west off the planned course - much more close to the coast compared to the planned route





# 3. FACTUAL INFORMATION

## 3.1 The Accident


When the Ship is deemed to be sailing too close to the coast the **SEQUENCE OF SHIP MASTER'S ORDERS** is the following:

- 1) "hard to starboard" and the Ship's bow avoids the shallows;
- 2) "hard to port", but the Ship's stern cannot avoid them

**09.45 pm : COLLISION** between the port side of the hull and the eastern rock of "Le Scole"

- 3) "hard to starboard" and the ship speed reduces instantly up to 8,3 knots, drifting off in headway, on a heading of 350°

**IMMEDIATELY the two Ship's main electrical engines lose power**



# 3. FACTUAL INFORMATION

## 3.1 The Accident

### WEATHER CONTITIONS ON SCENE ACCIDENT

*«...Northern Tyrrhenian Sea: changeable 3 rotating from north-east and increasing - partly cloudy - good visibility ....»*

*At 09.00 pm the Monte Argentario weather station records «wind blowing from East-North-East at a speed of 17 knots that intensifies up to 19 knots at 11.00 pm»*



**Source** : Mediterranean weather bulletin, issued at 18:00/utc of Friday, 13<sup>th</sup> January 2012 and valid till 06:00/utc of Saturday 14<sup>th</sup> January 2012 - Centro Nazionale di Meteorologia e Climatologia Aeronautica



# 3. FACTUAL INFORMATION

## 3.1 The Accident

### At 09.50 pm : **black-out onboard**

- the emergency generator turns on, but is unable to connect with the emergency electrical panel
- the two rudders are starboard;
- the supplementary batteries guarantee only the functioning of the emergency lighting and shipboard internal communication appliances
- the Bridge instruments work thanks to the dedicated batteries (UPS)
- the computer containing the software to calculate the stability (NAPA) is out of order

### At 09.55 pm : **the engine crew department gets aware about the flooding**

- *Chief Engineer informs the personnel on bridge about the flooding in the two contiguous generators rooms (bow and stern - **compartment 6 and 7**)*
- the 2<sup>nd</sup> Engineer assesses the flooding into the Propulsion Engine Motor (PEM) room too (**compartment 5**) - *Message is passed on to the bridge.*
- the Chief Mate informs, via UHF, the Staff Captain about the flooding of 3 contiguous compartments (generators rooms at the bow, generators room at the stern and PEM room (compartments 5, 6 e 7));



### *During 10-15 minutes following the impact*

- Ship Master is informed directly about the flooding. No orders from him.
- **Inspection activity** in the watertight compartments carried out by the Chief Mate and the Staff Engineer

*Assessment:* Deck A - water flow leaking out through the watertight door n.24. **Compartment n. 4 is flooding**

### **Ship's position at 10.11 pm**

- steady (0.3 knots)
- 42°22'24"N 010°55'36"E
- starting to drift and to list her bow to starboard, south-westward due to the combined influence of the **north-east wind** and the **helm hard to starboard**.




# 3. FACTUAL INFORMATION

## 3.1 The Accident

At 10.12 pm

### Leghorn Maritime Rescue Sub-center Control (MRSC)

- detects the Ship in proximity of the Island of Giglio (Punta Lazzaretto).
- tries to contact the Ship. Someone onboard (unknown identity) informs about the black out onboard.




# 3. FACTUAL INFORMATION

## 3.1 The Accident

At 10.34 pm

The ship reports that the heeling is increasing and declares the “**DISTRESS**”

The MRSC requests information on the number of persons on board.





# 3. FACTUAL INFORMATION

## 3.1 The Accident


**At 10.39 pm**

“Patrol boat G 104” (designated O.S.C. – On Scene Commander), being alongside the ship, informs Leghorn M.R.S.C. about the Ship’s stern heaviness, and at 10.44 pm she is laying on her starboard;

Weather conditions are good

**At 10.40 pm (09.40 pm UTC)**

the Ship launches the distress through INMARSAT “C” (1530 – 75 tracks).




# 3. FACTUAL INFORMATION

## 3.1 The Accident

At 10.58 pm

Almost in **final grounded position**, struck, Lat  $42^{\circ}21'50''\text{N}$  – Lon  $010^{\circ}55'18''\text{E}$   
*Island of Giglio – Cala del Lazzereto*



# 3. FACTUAL INFORMATION

## 3.1 The Accident

- **10.58 pm** : the Ship Master informs the Coast Guard that he orderded **Abandon Ship**
- **11.37 pm**: Livorno M.R.S.C. calls the Ship Master. He reports the presence of about 300 persons (passengers and crew) on board.
- **00.32 am**: The Ship Master communicates that some persons are overboard, into the starboard side seawater, to be rescued.
- **00.34 am**: The Ship Master tells Livorno M.R.S.C. to be onboard a survival craft and is seeing other persons overboard, into water, on the starboard side.
- **00.36 am**: The “Patrol boat G 104” reports to Livorno M.R.S.C. the presence of 70-80 persons, at least, onboard.
- **00.41 am**: The ship has a 80° list, about 50 persons cannot leave the ship.
- **00.53 am**: Start of helicopters rescue operations. Other assets, already dispatched on the scene, keep on rescuing castaways.
- **01.11 am**: Leghorn M.R.S.C. contacts the Ship Master who tells to be ashore, on the Island.





*The pictures were taken from the Island of Giglio  
the image does not correspond to the present history of events, but it is noteworthy for showing the exact  
moment when the lifeboats are launched on the starboard side*



# 3. FACTUAL INFORMATION

## 3.1 The Accident

- **01.46 am:** Leghorn M.R.S.C intimates the Ship Master to go onboard the Ship and to give an account of the actual situation
- **03.44 am :** 40-50 persons at least are onboard
- **04.22 am :** 30 persons are still onboard
- **04.39 am:** On Leghorn M.R.S.C. request, the “Patrol boat G.104” reports the ship’s position -  $42^{\circ}21'.36N$   $010^{\circ}55'.12E$ , laying on a 27 meters bottom






# 3. FACTUAL INFORMATION

## 3.1 The Accident

### SHIP'S LAST POSITION



















# 3. FACTUAL INFORMATION


## 3.1 The Accident

- ❑ Intense activity of assistance to the castaways from rescuers and the local population.
- ❑ Retrieving of persons from water

14<sup>th</sup> January, at 04.00 am:

- Search operations at sea and on board the ship
- Transfer operations of survivors by local ferry.
- Counting and identification of passengers and crew operations

- ❑ Underwater search operations report, so far, 30 bodies - found mainly at deck no. 4 and close to the keel. Two persons still missing.



# 3. FACTUAL INFORMATION

## OVERVIEW - HISTORY of EVENTS

## 3.1 The Accident

TIME	EVENT	HEELING	EVIDENCE from
09.45 pm	Collision with the Scaev reefs		A.I.S.
09.50 pm	Black-out onboard		Crew
10.36 pm	Ship drifting	05°	Crew
10.44 pm	Ship touches the sea bottom	12°	Patrol boat "G 104"
10.48 pm	General Emergency		Witness ashore
10.55 pm	First lifeboat launched at sea		Patrol boat "G 104"
10.58 pm	Ship grounding	15°	Ship Master
11.37 pm	440 persons still to evacuate	20°	Livorno Coast Guard
00.34 am	Ship master leaves the Ship by lifeboat	70° - 75°	Ship Master
00.41 am	Helicopter ITCG intervention to recover 50 persons	80°	Livorno Coast Guard
03.44 am	50 persons still to evacuate		Livorno Coast Guard
04.22 am	30 persons still to evacuate		Livorno Coast Guard
06.14 am	Evacuation completed		Livorno Coast Guard







# 3. FACTUAL INFORMATION




















## 3.2 Crew Members

### CREW MEMBERS

- ❑ The TOTAL CREW onboard were composed of 1023 members whose  
838 with direct/active roles set in the Muster List
  
- ❑ *MUSTER LIST*  
Crew members with roles in the Muster List were trained according to the “Basic training” certification (Ref. STCW 78-95 – Regulation VI/2)



# Nationality of the crew members (no.1023 persons)

NATIONALITY		NO. OF CREW MEMBERS
AUSTRIA		3
BELGIO		1
BRASILE		6
BULGARIA		7
CHILE		2
CHINA		20
COLOMBIA		10
CROAZIA		1
DOMINICAN REPUBLIC		7
FRANCE		1
GERMANY		5
GREAT BRITAIN		12
GUATEMALA		6
HONDURAS		17
HUNGARY		6
<b>INDIA</b>		<b>202</b>
<b>INDONESIA</b>		<b>170</b>
<b>ITALY</b>		<b>150</b>
UKRAINE		2

NATIONALITY		NO. OF CREW MEMBERS
JAMAICA		2
JAPAN		1
MOLDOVIA		1
MYANMAR		1
NEPAL		1
PARAGUAY		2
PERU'		45
<b>PHILIPPINES</b>		<b>294</b>
POLAND		3
ROMANIA		26
RUSSIAN FEDERATION		3
SERBIA		1
SLOVAKIA		1
SLOVENIA		1
SOUTH KOREA		2
SPAIN		7
SRI LANKA		1
SYRIA		1
VIETNAM		3

# 3. FACTUAL INFORMATION

## 3.2 Passengers

### Italian Decree 13 October 1999

implementing Directive 98/41/EC on the registration of persons sailing on board passenger ships operating to or from ports of the Member States of the Community and the provisions set in Reg III/27 of SOLAS Convention

- At the moment of the accident 4229 persons were onboard, as follows:

Passenger information  
fully recorded on a  
system approved by the  
Administration

TOTALE QUANTITA' VERIFICATE ALLE: : _20:04_ (ORA)		TOTAL QUANTITIES VERIFIED AT: _____ (TIME)
Adulti (> 12 anni) Adults (over 12 years)		2954
Bambini (da > 3 a ≤ 12 anni) Children (fm > 3 to ≤ 12 years)		200
Neonati (da 0 a ≤ 3 anni) Infants (fm 0 to ≤ 3 years)		52
Bisognosi di Assistenza Needing Assistance		19
TOTALE OSPITI TOTAL GUESTS		3206
TOTALE EQUIPAGGIO TOTAL CREW		1023
TOTALE PERSONE A BORDO TOTAL SOULS ON BOARD		4229



# 3. FACTUAL INFORMATION

## 3.2 Passengers

### Nationality of passengers (no. 3206 persons)

**ITALY (989),  
GERMANY (568),  
FRANCE (462),  
SPAIN (177),  
U.S. (129),  
CROATIA (127),  
RUSSIA (108),  
AUSTRIA (74),  
SWISS (69),  
BRASIL (46),  
JAPAN (46),  
HOLLAND (42),  
UKRAINE (33),  
KOREA (30),  
ROMANIA (29),  
HONG KONG (26),  
GREAT BRITAIN (25),  
AUSTRALIA (21),  
ARGENTINE (17),  
TAIWAN (13),  
CANADA (12),**

**CHINA (12),  
PORTUGAL (11),  
COLOMBIA (10),  
CHILE (10),  
TURKEY (9),  
BELGIUM (8),  
ISRAEL (8),  
KAZAKHSTAN(8),  
PERU' (8),  
POLOAND (8),  
MOLDOVA (6),  
NEPAL (6),  
SWEDEN (5),  
VENEZUELA (5),  
DENMARK (4),  
DOMINICAN REPUBLIC(4),  
SERBIA (4),  
SOUTH AFRICA (4),  
NETHERLANDS ANTILLES (3),  
BELARUS (3),  
GREECE (3),**

**HUNGARY (3),  
IRAN (3),  
EIRE (3),  
MACEDONIA (3),  
ALBANIA (2),  
CUBA (2),  
ALGERIA (2),  
EQUADOR (2),  
MEXICO (2),  
FINLAND (2),  
ANDORRA (1),  
BULGARIA (1),  
BOSNIA (1),  
CZECH REPUBLIC (1),  
INDIA (1),  
MOROCCO (1),  
NORWAY (1),  
NEW ZELAND(1),  
PHILIPPINES (1),  
URUGUAY (1).**



# 3. FACTUAL INFORMATION

## 3.2 Passengers

- VICTIMS: No. 32
- NATIONALITY:
  -  Germany (12)
  -  Italy (7)
  -  France (6)
  -  Peru (2)
  -  United States (2)
  -  Hungary (1)
  -  Spain (1)
  -  India (1)





# 3. FACTUAL INFORMATION

## 3.3 Survival Crafts

### LIFE SAVING APPLIANCES - LIFEBOATS/LIFERAFTS-



- 26 lifeboats
- 23 the launched ones
- 3 lifeboats on portside could not be launched due to the significant list of the vessel

- 6 Liferrafts were launched



# 3. FACTUAL INFORMATION

## 3.3 Survival Crafts







# TABLE OF CONTENTS

1. ITALIAN MARITIME INVESTIGATIVE BODY

2. INVESTIGATIVE ACTIVITIES - *Preamble*

3. FACTUAL INFORMATION

*3.1 The Accident*

*3.2 Crew members*

*3.3 Passengers*

*3.4 Survival Crafts*

4. ANALYSIS

*4.1 Methodology of C/s Costa Concordia Marine Accident Investigation*

*4.2 Ship Stability in damage condition – NAPA Simulation on C/s Costa SERENA*

5. INVESTIGATION UNDERWAY



*5.1 Preliminary remarks*

*5.2 Issues still under investigation*



# 4. ANALYSIS


## 4.1 Methodology of C/s Costa CONCORDIA Marine Accident Investigation




# 4. ANALYSIS

## 4.1 Methodology of C/s Costa CONCORDIA Marine Accident Investigation

STEP 3



STEP 4






# 4. ANALYSIS

## 4.1 Methodology of C/s Costa CONCORDIA Marine Accident Investigation

STEP 5



# 4. ANALYSIS

## 4.2 Ship Stability in damage condition


NAPA Simulation on C/s Costa SERENA

12th February 2012

**Damage between frame no. 58 and frame no. 125/128,  
creating a 60 meters hole into the hull – portside**

- **The two most affected watertight compartments (contiguous), immediately flooded:**
  - no. 5 (Propulsion Electric Motor)
  - no. 6 (aft generators)
- **Partially flooded at the time of crew inspection (10 minutes after the impact)**
  - no. 7 (forward generators)
  - no. 4 (Galley compressors)





DESCRIZIONE POMPE

DECK	FRAMES	NAME OF PUMP	CAPACITY/HEAD
PONTE	ORD.	NOME DELLA POMPA	PORTATA/PREVALENZA




REMOTE CONTROLLED SHELL


ITEM	PIECE NUMBER	SERVICE DESCRIPTION
Nr.	MARCAPEZZO	DESCRIZIONE DEL SERVIZIO

# Costa Serena simulation after the impact – Damage condition 0


## Compartment no. 5 flooded immediately 2287.1 t of water



# Damage condition after 20 minutes inflowed water 6419.1 t



# Damage condition after 50 minutes inlooded water 6588.0 t



BMmax is...



# Damage condition after 70 minutes inflowed water 6836.5 t

Active Loading Condition DAMAGCOND70MIN [2012-02-10 16:23]

File Task Damage Results Tools View Loads Help **Damage stability criteria NOT MET!** Ack Log... **Offline**

Task  
Load Tanks  
Load Stores  
Damage

Results  
Stab/Strength...  
Load Summary...

Damage  
Calculate  
Stages 0  
Reset...  
Ground...  
Stages  
Equilibr.

# 170

Damage Results

Res. to progr.fld : 0.36 M  
Critical openings due to progr.fld : P1DKOP  
first immersing : P1DK1P  
Heeling angle : 7.12 DEG  
Flooding angle : 22.09 DEG  
Minimum freebrd : -1.67 M  
GM intact : 1.52 M  
GM actual : 0.87 M  
Maximum GZ : 0.44 M  
Range of pos. GZ : 15.0 DEG  
Inflowed water : 6836.5 T  
Determining crit.: MARGIN  
Min. GM required : 0.70 M  
Status : NOT MET

Damage Details

Selected tank group: A11

Name	Capacity [m3]	Vrel [%]	Volume [m3]	Density [t/m3]	Weight [t]	Frm [tm]	Status	Flood water [m3]
R05A01P	166.8	100.0	166.8	1.025	171.0	0	open to	140.2
R05A01S	166.8	100.0	166.8	1.025	171.0	0	open to	33.2
R06A01P	258.2	100.0	258.2	1.025	264.7	0	open to	219.2
R06A01S	231.4	100.0	231.4	1.025	237.2	0	open to	64.7
	81977		22233		22495	****		6650.5

Dens 1.028 t/m3

11.33  
At marks  
Below keel Mid 9.11 7.65  
6.90

Heel P 7.12 deg GM 2.09 m DW 23872 t BMmax 330 % at fr. 87  
Trim A 3.04 m GMreq 1.50 m UnkDWT 0.5 % SFmax 182 % at fr. 126  
Defl. hog 0.03 m F GMcorr -0.29 m Disp 68127 t

# Damage condition after 90 minutes inflowed water 13937.8 t

Active Loading Condition DAMAGCOND90MIN [2012-02-10 16:25]

File Task Damage Results Tools View Loads Help **Damage stability criteria NOT MET!** Ack Log... **Offline**

Task  
Load Tanks  
Load Stores  
Damage

Results  
Stab/Strength...  
Load Summary...

Damage  
Calculate  
Stages 0  
Reset...  
Ground...  
Stages  
Equilibr.

# 170

Damage Results

```

Res. to progr.fld : -0.49 M
Critical opening ...
due to progr.fld : P1DKOP
Heeling angle : 5.13 DEG
Flooding angle : 0.00 DEG
Minimum freebrd : -2.10 M
GM intact : 2.06 M
GM actual : 1.30 M
Maximum GZ : -0.03 M
Range of pos. GZ : 0.00 DEG
Inflowed water : 13937.8 T
Determining crit.: INTRANGE
Min. Gm required : 0000.0 M
Status : NOT MET
    
```

Damage Details

Name	Capacity [m3]	Vrel [%]	Volume [m3]	Density [t/m3]	Weight [t]	Frm [tm]	Status	Flood water [m3]
R05A01P	166.8	100.0	166.8	1.025	171.0	0	open to	156.6
R05A01S	166.8	100.0	166.8	1.025	171.0	0	open to	87.5
R06A01P	258.2	100.0	258.2	1.025	264.7	0	open to	239.3
R06A01S	231.4	100.0	231.4	1.025	237.2	0	open to	134.7
	81977		25902		26256	75225		13555

Dens 1.028 t/m3

11.11  
At marks  
Below keel  
11.54 Mid 9.51 7.46  
7.91


Heel P 5.15 deg  
Trim A 4.25 m  
Defl. hog 0.03 m F

GM 2.09 m  
GMreq 1.50 m  
GMcorr -0.25 m

DW 27633 t  
UnkDWT 0.5 %  
Disp 71887 t

BMmax 417 % at fr. 88  
SFmax 220 % at fr. 126

# Damage final condition inflowed water **17641.2 t**



# TABLE OF CONTENTS

1. ITALIAN MARITIME INVESTIGATIVE BODY
2. INVESTIGATIVE ACTIVITIES - *Preamble*
3. FACTUAL INFORMATION
  - 3.1 *The Accident*
  - 3.2 *Crew members*
  - 3.3 *Passengers*
  - 3.4 *Survival Crafts*
4. ANALYSIS
  - 4.1 *Methodology of C/s Costa Concordia Marine Accident Investigation*
  - 4.2 *Ship Stability in damage condition – NAPA Simulation on C/s Costa SERENA*
5. INVESTIGATION UNDERWAY
  - 5.1 *Preliminary remarks*
  - 5.2 *Issues still under investigation*



# 5. INVESTIGATION UNDERWAY

## 5.1 Preliminary remarks

- ❑ **Critical point - delay in sounding the "General Emergency" alarm and taking timely steps to abandon the ship**
  
- ❑ Organization of the abandonment of the ship was **on the whole appropriate** to manage an emergency such as the one that occurred a Giglio Island





# 5. INVESTIGATION UNDERWAY

## 5.1 Issues still under investigation

### CREW MANNING

- Recruitment of crew members
- Muster List arrangement
- Management of “Complementary” personnel
- Familiarization with emergency tasks/roles

### VOYAGE

- Navigation planning
- Bridge asset
- “Master Com” procedure



# 5. INVESTIGATION UNDERWAY

## 5.1 Issues still under investigation



STABILITY

- Leak assessment
- Flooding dynamics
- Ship response capacity to flooding
- Watertight compartment system



BLACK OUT

- Loss of electric power
- Loss of electric power distribution
- Emergency electric source



# 5. INVESTIGATION UNDERWAY

## 5.1 Issues still under investigation



### GENERAL EMRGENCY MANAGEMENT

- Internal communication
- Emergency timing
- Bridge team crisis response



### SAFETY EQUIPMENTS

- Survival crafts and rescue boats
- Effects of the progressive ship asset on the evacuation procedure
- Ship evacuation timing



# 5. INVESTIGATION UNDERWAY

## 5.1 Issues still under investigation

SHIP DEVICES/  
CAPABILITY TO PUT IN  
PLACE AN ADEQUATE  
RESPONSE TO THE  
EMERGENCY

- Devices Arrangement
- Devices Vulnerability
- Devices Interoperability
- Redundancies





**THANKS FOR YOUR ATTENTION**

ITALIAN MARITIME INVESTIGATIVE  
BODY ON MARINE ACCIDENTS

---





**ANY QUESTION OR REQUEST FOR  
CLARIFICATION MAY BE ADDRESSED  
BY MAIL TO**

**[investigative.body@mit.gov.it](mailto:investigative.body@mit.gov.it)**